

15<sup>th</sup> May, 2009

Ref No

Dated

To,

The Principal,  
DAV Sr. Sec Public School,  
Dengra Road, Tohana.

**Sub: Certificate regarding Building work of Junior Block in DAV School Campus-Tohana.**

Dear Sir,

The work executed by M/s Vijay Kumar Contractor for the above cited building is as per standard building norms following HSR schedule of rates / specifications to the satisfaction of undersigned and as per architectural & structural drawings supplied.

The information is placed for necessary action at your end please.

Thanking you,

Sincerely yours,



For Ar. C.B. Anand

D.A.V Public School Tohana



हरियाणा लोक निर्माण विभाग (भवन व मार्ग शाखा)

प्रेषक : उपमण्डल अभियन्ता  
लो. नि. वि. (भवन तथा मार्ग शाखा)  
टोहाना।

प्रेषित : खण्ड शिक्षा अधिकारी  
टोहाना।

क्रमांक. 339

दिनांक 14/3/2013

विषय : शहर टोहाना में समस्त प्राइवेट स्कूलों के भवनों का निरीक्षण करने बारे।

संदर्भ : उपमण्डल अधिकारी(ना0) टोहाना के पत्र क्रमांक 4093-97/रतैनो दिनांक शुन्य के संदर्भ में

उपरोक्त विषय के बारे में उपमण्डल अधिकारी(ना0) टोहाना के आदेश पर आपके द्वारा, उपमण्डल अभियन्ता पंचायती राज व हस्ताक्षरकर्ता द्वारा जिन प्राइवेट स्कूलों के भवनों का निरीक्षण किया गया था। उसकी सुची हस्ताक्षरकर्ता द्वारा हस्ताक्षर करके आपके कार्यालय को आगामी कार्यवाही हेतु भेजी जाती है।

रह/सुची

15/3/2013

उपमण्डल अभियन्ता,  
लो. नि. वि. (भवन तथा मार्ग शाखा)  
टोहाना।

01. - बरौंड जिला शिक्षा अधिकारी टोहाना  
क्रमांक - 17-11/13/5252/5361

दिनांक - 15/3/13

स्कूल की छति बरौंड के उपमण्डल उच्च स्कूलों के सेवा में आवरणक कार्यालयी हेतु भेजा है

Block Education Officer  
Tohana (Fatehshah)

**1) Saraswati Vidya Mandir, Tohana:**

The structure of the building visible seems to be safe upto 3<sup>rd</sup> floor, but not safe to sustain Earth Quakes also room of 3<sup>rd</sup> floor has to be vacated as RBC slab of room is not safe.

**2) Rayan Convent School, Tohana:**

The structure of the building visible seems to be safe upto IInd storey.

**3) Bairang Model School, Tohana:**

The structure of the building visible seems to be safe, but not safe against Earth Quakes.

**4) K.M. Sr. Sec. School, Tohana:**

The structure of the building require some addition to beam and column and ground floor of both new and old block for which necessary steps has been told to the authorities to the School Management. The Building is not safe for Earth Quakes vibration.

**5) K.M. Model School, Tohana:**

The Building structure seems to be safe for existing storey i.e. ground floor plus two storey building.

**6) DAV Public School, Tohana:**

The structure of the building 3<sup>rd</sup> floor are visibly safe and constructed as per design to counter Earth Quacks forces upto IInd floor.

**7) Durga Mahila Sr. Sec. School, Tohana:**

The building structure seems to be safe, but not able to with stand against Earth Quakes.

**8) Adrash Public School, Tohana:**


The structure of the building seems to be safe, but urgent replacement of the floor and ground floor slab required. As building is not able to with stand against Earth Quakes.

**9) Little Angel School, Tohana:**

The building seems to be safe upto IInd storey, but not safe against Earth quakes forces.

Sub Divisional Officer  
Panchayati Raj, Tohana

  
Sub Divisional Officer  
Tohana (Panchayat)  
  
15/12/13

  
Sub Divisional Engineer  
Provincial Sub Division  
PWD B&R Br., Tohana